

PCCables.com, Inc. declares that we do not intentionally add any of the following substances listed in Directive 2015/863/EU (RoHS3) to the products we supply. To the best of our knowledge, our suppliers do not intentionally add any of the following substances listed in Directive 2015/863/EU (RoHS3) to the products we purchase unless otherwise specified on the certificate of conformance provided with the product upon purchase.

In 2015, Directive 2015/863 was issued by the EU – adding four (4) additional restricted substances to the original directive restricting the use of six (6) for a total of ten (10) restricted hazardous substances.

The ten (10) hazardous substances are as follows:

Lead < 1000ppm

Mercury <1000 ppm

Cadmium <100 ppm

Hexavalent chromium <1000 ppm

Polybrominated Biphenyls (PBB) <1000 ppm

Polybrominated Diphenyl Ethers (PBDE) <1000 ppm

Bis (2-Ethylhexyl) phthalate (DEHP) <1000 ppm

Benzyl butyl phthalate (BBP) <1000 ppm

Dibutyl phthalate (DBP) <1000 ppm

Diisobutyl phthalate (DIBP) <1000 ppm

This statement is based on the knowledge as of this date of issue and PCCables.com, Inc. makes no warranties, expressed or implied, and assumes no liability in connection with the use of this information.

PCCables.com Inc. has confirmed that Part Number:

71013 DB9-F to RJ45 Cable Cisco Router Console

Passes the (RoHS 3.0) 2015/863/EU Compliant Tests. We accomplish by testing and quality control at the factory. Official Factory Material Tests Available on Request. Email support@pccables.com.

Confirmed by:

Jay F Kullmann/QA Dept PCCABLES.COM Inc.

Date:02/24/2020

Additional Information: <https://www.rohsguide.com/rohs3.htm>

<https://www.pccables.com/Products/71013.html>